

CLAIMED "SIDE" COIL SUPPORTS ARE NOT DISCLOSED IN LASKARIS





Fig. 6

- Plate 60 braces sides of coil.
- A side of a coil is parallel to rotor axis



LASKARIS FIG 3.

- Coil side is not braced by coil housing that rather braces coil end surface.

09/854,940